

CARILLION CORE FORM HEALTH, SAFETY, SUSTAINABILITY AND QUALITY

Making tomorrow a better place

HSSQ Alert Template CORE/HSSQ/PRO/033-F001

Business:	Construction Services		ALERT
		Deference No.	
Title:	Hitachi ZX85 Excavators	Reference No:	CCS 185
Issue Date:	12 th May 2016	Issued By:	Geoff Lee
Type of Alert:	Health & Safety		
Subject:	Failure of Excavator Boom		
Who is affected:	All sites		
	Sheared Ram should be will be should be will be should b		
Details:	An arm cylinder bracket/component failure to an 8T Hitachi Excavator <u>Type ZX85</u> occurred on one of our sites whilst excavating.		
	The excavator, fitted with a ditching bucket, was excavating a shallow trench when the lugs of the front dipper arm sheared (at top arm cylinder bracket).		
	Visual investigation has suggested steelwork material failure (fatigue) to the lug/s (not the welds).		
Action Required:	Stand down all Hitachi ZX85 excavators and contact your supplier		
Further Information:	Carillion Managed Plant have raised this issue with the plant supply chain to ensure these models are not delivered to site		
	Hitachi ZX85 Failure product alert		
	Hitachi Service information letter		
Original Source:	Carillion incident		
Method for confirming that actions have been taken:	Check to ensure that this model of excavator is not in use.		

<< Contract Head to complete >>

Local Action Taken: