



Health and Safety Issue - Carbon Monoxide (CO) Fumes



Street Lighting

We have recently taken delivery of 7 new vehicles from Aldercote and have experienced an issue whereby carbon monoxide fumes are getting into the cab which has resulted in a member of our ops team being treated for carbon monoxide poisoning, pleased to say he is fine but still not a nice situation.

The issue has come about due to the vicinity of the exhaust to the box section of the stabilising leg (picture attached), the fumes are coming up through the box section and filling the cab.

As a result of this the vehicles that we have recently received have been grounded by our Ops manager until the problem is resolved. We have spoken with the manufacturer and H&S teams who are reviewing what's happened.