

Safety alert – Pass Safe Sign Pole – Fibre Glass

Sign collapse because of high winds. The post were 168mm Glass fibred Pass safe poles. At this point considering investigating the condition of all similar poles. Not sure if there is a particular structural test that we can undertake but I am trying to contact test houses to see if there is anything we should be doing to prevent this type of failure. The sign poles were approx. 15 years old.



Safety alert – Pass Safe Sign Pole – Fibre Glass

