



Flash Alert

IP Central

Flash Alert	Event	Compressor Unloading Incident		
Date & Time of Report:	Date:	08/02//2016	Time:	12:15
Date & Time of Events:	Date:	05/02/2016	Time:	09:30
Project:	IPEM			
Location:	Kirkby in Ashfield Station			
Description / Nature of event:	<p>A 400Kw compressor was being unloaded from its transporter by the Speedy Hire driver. The straps securing the compressor had been removed, but the tow eye had become siezed in the tow hitch fixed to the transporter headboard.</p> <p>The driver and an operative forced the tow eye from the hitch, when the compressor sprung loose. It rolled off the transporter bed, down the trailer ramps and travelled an aditional 5m across the compound. It came to rest when it collided with a metal storage container.</p>			
	 <p>The incident is still under investigation.</p>			
Details of Principal Contractor / Sub Contractor / Company	PC – J Murphy & Sons Ltd Plant Hire Company – Speedy Hire			

Flash Alert

IP Central

Flash Alert	Event	Excavator Loading Incident		
Date & Time of Report:	Date:	08/02//2016	Time:	12:00
Date & Time of Events:	Date:	27/01/2016	Time:	16:50
Project:	IPEM			
Location:	Wing Viaduct			
Description / Nature of event:	<p>A 38T excavator belonging to L Lynch Plant Hire Ltd, was being collected from site by the hire company. The transporter was driven to site by an L Lynch Plant Hire driver, who was on his own. The driver had some difficulty in siting the transporter for him to load the excavator.</p>  <p>The driver loaded the excavator at an angle to the transporter ramps, when the excavator lost traction and drove off the trailer bed.</p> <p>The incident is still under investigation.</p>			
Details of Principal Contractor / Sub Contractor / Company	PC – J Murphy & Sons Ltd Plant Hire Company – L Lynch Plant Hire Ltd			